


Profile
HA, HB, HC, HD, SPB, SPC,
H36, HL, HM,



Profile
HB, 15J, 25J,

FARMBELT		Dost pne długo ci
50x30 DP	Lw	2240 - 15000
HA/F -P	Lw	630 - 7000
HA/F -K	Lw	630 - 7000
HB/F -P	Lw	2000 - 15000
2-HB/F -P	Lw	2000 - 15000
3-HB/F -P	Lw	2000 - 15000
4-HB/F -P	Lw	2000 - 15000
5-HB/F -P	Lw	2000 - 15000
6-HB/F -P	Lw	2000 - 15000
7-HB/F -P	Lw	2000 - 15000
8-HB/F -P	Lw	2000 - 15000
HB/F -K	Lw	2000 - 15000
2-HB/F -K	Lw	2000 - 15000
3-HB/F -K	Lw	2000 - 15000
4-HB/F -K	Lw	2000 - 15000
5-HB/F -K	Lw	2000 - 15000
6-HB/F -K	Lw	2000 - 15000
7-HB/F -K	Lw	2000 - 15000
8-HB/F -K	Lw	2000 - 15000
HC/F -P	Lw	2100 - 15000
2-HC/F -P	La	2800 - 12500
3-HC/F -P	La	2800 - 12500
4-HC/F -P	La	2800 - 12500
5-HC/F -P	La	2800 - 12500
6-HC/F -P	La	2800 - 12500
7-HC/F -P	La	2800 - 12500
8-HC/F -P	La	2800 - 12500
9-HC/F -P	La	2800 - 12500
10-HC/F -P	La	2800 - 12500
HC/F -K	Lw	2100 - 15000
2-HC/F -K	La	2800 - 12500
3-HC/F -K	La	2800 - 12500
4-HC/F -K	La	2800 - 12500
5-HC/F -K	La	2800 - 12500
6-HC/F -K	La	2800 - 12500
7-HC/F -K	La	2800 - 12500
8-HC/F -K	La	2800 - 12500
9-HC/F -K	La	2800 - 12500
10-HC/F -K	La	2800 - 12500

H25/F -P	Lw	2000 - 15000
H25/F -K	Lw	2000 - 15000
HD/F -P	Lw	2240 - 15000
HD/F -K	Lw	2240 - 15000
HDM/F -P	Lw	2240 - 5000
HDM/F -K	Lw	2240 - 5000
D/F Miklon -P	Lw	2500 - 15000
D/F Miklon -K	Lw	2500 - 15000
E/F Miklon -K	Lw	2500 - 15000
SPA/F -P	Lw	630 - 7000
2-SPA/F -P	La	1600 - 5600
3-SPA/F -P	La	1600 - 5600
4-SPA/F -P	La	1600 - 5600
5-SPA/F -P	La	1600 - 5600
6-SPA/F -P	La	1600 - 5600
7-SPA/F -P	La	1600 - 5600
8-SPA/F -P	La	1600 - 5600
28-SPA/F -P (Wickel)	La	1600 - 5600
SPA/F -K	Lw	1600 - 7000
2-SPA/F -K	La	1600 - 5600
3-SPA/F -K	La	1600 - 5600
4-SPA/F -K	La	1600 - 5600
5-SPA/F -K	La	1600 - 5600
6-SPA/F -K	La	1600 - 5600
7-SPA/F -K	La	1600 - 5600
8-SPA/F -K	La	1600 - 5600
SPB/F -P	Lw	2000 - 15000
2-SPB/F -P	La	2000 - 7000
3-SPB/F -P	La	2000 - 7000
4-SPB/F -P	La	2000 - 7000
5-SPB/F -P	La	2000 - 7000
6-SPB/F -P	La	2000 - 7000
7-SPB/F -P	La	2000 - 7000
8-SPB/F -P	La	2000 - 7000
SPB/F -K	Lw	2000 - 15000
2-SPB/F -K	La	2000 - 7000
3-SPB/F -K	La	2000 - 7000
4-SPB/F -K	La	2000 - 7000
5-SPB/F -K	La	2000 - 7000
6-SPB/F -K	La	2000 - 7000
7-SPB/F -K	La	2000 - 7000
8-SPB/F -K	La	2000 - 7000

SPC/F -P	Lw	2500 - 15000
2-SPC/F -P	La	2500 - 15000
3-SPC/F -P	La	2500 - 15000
4-SPC/F -P	La	2500 - 15000
5-SPC/F -P	La	2500 - 15000
6-SPC/F -P	La	2500 - 15000
7-SPC/F -P	La	2500 - 15000
8-SPC/F -P	La	2500 - 15000
9-SPC/F -P	La	2500 - 15000
10-SPC/F -P	La	2500 - 15000
SPC/F -K	Lw	2500 - 15000
2-SPC/F -K	La	2500 - 15000
3-SPC/F -K	La	2500 - 15000
4-SPC/F -K	La	2500 - 15000
5-SPC/F -K	La	2500 - 15000
6-SPC/F -K	La	2500 - 15000
7-SPC/F -K	La	2500 - 15000
8-SPC/F -K	La	2500 - 15000
9-SPC/F -K	La	2500 - 15000
10-SPC/F -K	La	2500 - 15000
16-SPC/F -K (Wickel)	La	2500 - 15000
H36/F -P	Lw	1120 - 2240
H36/F -K	Lw	1120 - 2240
HL/F -P	Lw	1900 - 5000
HL/F -K	Lw	1900 - 5000
HM/F -P	Lw	2000 - 5000
HM/F -K	Lw	2000 - 5000
5V/15-J/F -P	Lw	2000 - 15000
2-15J/F -P	Lw	2000 - 15000
3-15J/F -P	Lw	2000 - 15000
4-15J/F -P	Lw	2000 - 15000
5-15J/F -P	Lw	2000 - 15000
6-15J/F -P	Lw	2000 - 15000
7-15J/F -P	Lw	2000 - 15000
5V/15-J/F -K	Lw	2000 - 15000
2-15J/F -K	Lw	2000 - 15000
3-15J/F -K	Lw	2000 - 15000
4-15J/F -K	Lw	2000 - 15000
5-15J/F -K	Lw	2000 - 15000
6-15J/F -K	Lw	2000 - 15000
7-15J/F -K	Lw	2000 - 15000
24-15J/F -K (Wickel)	Lw	2000 - 15000
15-25J/F -K	La	2800 - 12500
P - FARBELT ci gno z poliestru		
K - FARBELT ci gno aramidowe		
L=L - pasy gotowe do stosowania w zestawach		